Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
[3]	8	((Richard Charles) with Flaherty)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 15:30
L2	1	, ((Richard Charles) with Flaherty) and (photocontrol photosensor photocell)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 15:54
L3	2	((Richard Charles) with Flaherty) and (photocontrol photosensor photocell photo)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 15:56
L4	10001	(calibrate calibration calibrating adjust adjusting adjustment adjusted) with (photocontrol photosensor photocell photo)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 15:57
L5	1499	(calibrate calibration calibrating adjust adjusting adjustment adjusted) with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control)) and (switching switch relay relaying) and (light laser radiation beam) and (aperture opening hole)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:00
L6	134	(calibrate calibration calibrating adjust adjusting adjustment adjusted) with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control)) and (switching switch relay relaying) and (light laser radiation beam) and ((aperture opening hole) with angle)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:07
L7	212	((photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control)) with (light laser radiation beam) with (aperture opening hole)) and ((calibrate calibration calibrating adjust adjusting adjustment adjusted) with angle)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:12

L8	25	((photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control)) with (light laser radiation beam) with (aperture opening hole)) and ((calibrate calibration calibrating adjust adjusting adjustment adjusted) with angle with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:16
9	7	control))) ((photocontrol photosensor photocell (photo with sensor)) (photo with cell) (photo with control)) with (light laser radiation beam) with (aperture opening hole)) and ((calibrate calibration calibrating adjust adjusting adjustment adjusted) with angle with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control))) and (sensitivity with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with sensor) (photo with cell) (photo with control)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:18
L10	8	((photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control)) with (light laser radiation beam) with (aperture opening hole)) and ((calibrate calibration calibrating adjust adjusting adjustment adjusted) with angle with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control))) and ((leg mount mounting) with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with sensor) (photo with cell) (photo with control)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:19

L11	1	((photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control)) with (light laser radiation beam) with (aperture opening hole)) and ((calibrate calibration calibrating adjust adjusting adjustment adjusted) with angle with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control))) and ((leg mount mounting) with (sensitivity sensitive) with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with sensor) (photo with cell) (photo with control)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:42
L12	198	((calibrate calibration calibrating adjust adjusting adjustment adjusted) with angle with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:42
L13	124	((calibrate calibration calibrating adjust adjusting adjustment adjusted) same angle same (aperture hole opening) same (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR ,	ON	2004/12/08 16:47
LI4	15	((calibrate calibration calibrating adjust adjusting adjustment adjusted) with angle with (aperture hole opening) with (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:43
L15	16	((calibrate calibration calibrating adjust adjusting adjustment adjusted) same angle same (aperture hole opening) same (leg mount mounting) same (photocontrol photosensor photocell (photo with sensor) (photo with cell) (photo with control)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:49

L16	1	((calibrate calibration calibrating adjust adjusting adjustment adjusted) same angle same (aperture hole opening) same (leg with (mount mounting)) same (photocontrol photosensor photocell (photo with sensor)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/08 16:47
		(photo with cell) (photo with control)))				